

**TABLE 8
BUILDINGS CONTAINING ASBESTOS**

PARCEL	LOCATION	DESCRIPTION	FINDING
8	Bldg. 991	Exterior Siding	Asbestos assumed
9	Bldg. 4	Vinyl floor tile	Tested positive
9	Bldg. 6	Acoustical tile, pipe covering, vinyl floor tile	Tested positive
9	Bldg. 6	Transite panels	Asbestos assumed
9	Bldg. T-6	Vinyl floor tiles	Tested positive
10	Bldg. 60	Vinyl floor tiles, pipe covering and joint packing	Tested positive
10	Bldg. 70	Vinyl floor tile	Tested positive
10	Bldg. T-70	Vinyl floor tile	Tested positive
10	Bldg. 85	Vinyl floor tile	Tested positive
10	Bldg. 88	Vinyl floor tile, gasket material, water line covering, linoleum	Tested positive
10	Bldg. 90	Vinyl floor tile, exterior joint caulking	Tested positive
10	Bldg. 90	Exterior transite siding and transite pipe	Asbestos assumed
11	Bldg. 808	Vinyl floor tile	Tested positive
11	Bldg. 808	Fire doors	Asbestos assumed
11	Bldg. 812	Vinyl floor tile, pipe covering, woven tape and joint packing	Tested positive
11	Bldg. 812	Transite piping and exterior transite siding	Asbestos assumed
11	Bldg. 821	Roofing material	Tested positive
11	Bldg. 821	Transite piping	Asbestos assumed
11	Bldg. 823	Transite piping and transite siding	Asbestos assumed
12	Bldg. 806	Vinyl floor tiles	Tested positive
12	Bldg. 807	Vinyl floor tiles	Tested positive
12	Bldg. 807	Transite piping, space heaters	Asbestos assumed
13	Bldg. 804	Transite siding and transite piping	Asbestos assumed
13	Bldg. 805	Vinyl floor tile	Tested positive

**TABLE 8 (cont)
BUILDINGS CONTAINING ASBESTOS**

PARCEL	LOCATION	DESCRIPTION	FINDING
14	Bldg. 802	Vinyl floor tile	Tested positive
14	Bldg. 802	Transite piping	Asbestos assumed
14	Bldg. 803	Transite piping	Asbestos assumed
16	Bldg. 830	Pipe covering, joint packing, exhaust lines	Tested positive
16	Bldg. 833	Vinyl floor tile	Tested positive
16	Bldg. 833	Exterior transite siding	Asbestos assumed
16	Bldg. 834	Vinyl floor tile	Tested positive
17	Bldg. 840	Vinyl floor tile	Tested positive
17	Bldg. 840	Transite siding, transite piping	Asbestos assumed
19	Bldgs. 790, 792, 793, 794	Not surveyed	
19	Bldg. 796	Joint packing, pipe covering, vinyl floor tiles	Tested positive
19	Bldg. 796	Transite siding and fire doors	Asbestos assumed
20	Bldg. 701	Acoustical insulation	Tested positive
20	Bldg. 701	Exterior transite siding	Asbestos assumed
20	Bldg. 726	Vinyl floor tile, pipe covering, joint packing	Tested positive
20	Bldg. 738	Vinyl floor tile, pipe covering, joint packing	Tested positive
21	Bldgs. 670, 674, 675, 676, 680, 689, 772	Drywall, kitchen and storage room flooring	Tested positive
21	Bldgs. 670, 674, 675, 676, 680, 689, 772	Built –up roof material	Asbestos assumed
21	Bldgs. 772, 774, 775	Hallway floor tile	Tested positive
21	Bldgs. 772, 774, 775	Built-up roof material	Asbestos assumed
24	Bldgs. 645, 646	Vinyl floor tile	Tested positive
24	Bldgs. 645, 646	Exterior transite siding	Asbestos assumed
24	Bldg. 646	Transite piping on roof	Asbestos assumed

TABLE 8 (cont)
BUILDINGS CONTAINING ASBESTOS

PARCEL	LOCATION	DESCRIPTION	FINDING
24	Bldg. 690	Vinyl floor tile, pipe wrap	Tested positive
25	Bldg. 590	Vinyl floor tile, pipe covering	Tested positive
25	Bldg. 590	Transite pipe, transite sheeting, transite siding	Asbestos assumed