




Essex Environmental, Inc.

## ENVIRONMENTAL COMPLIANCE STATUS REPORT City of Oakland – Leona Quarry

<b>Date:</b>	September 22, 2005; 9:00 a.m. – 11:00 a.m.	
<b>Inspector:</b>	Vanessa Loverti (Essex Environmental)	
<b>Weather:</b>	Fog, approximately 60 degrees Fahrenheit, and winds approximately 0 to 5 mph.	

### ACTIVITY: Whipsnake Fence Inspection

Inspected the entire continuous fence line in the lower quarry as well as the two separate fences in the upper quarry on Campus Drive. Overall the fencing complied with the requirements of the project's Special Status Mitigation and Monitoring Plan.

The fence in the Ridgemont basin was inspected for possible collapse from water accumulation from recent rains. The fence appeared to be in good condition at this time (see photos).



*Fence line near swale*



*Ridgemont Basin overview*

### ACTIVITY: Communication

Met Bill Martin and discussed the fence situation in the Ridgemont Basin. We agreed that the fence should remain in place until all work has been completed despite water accumulating that might occur from heavy rains.

We also discussed and agreed that the lower fence on the lower northwestern slope could be removed assuming that all construction is complete in that area.