




Essex Environmental, Inc.

## ENVIRONMENTAL COMPLIANCE STATUS REPORT

### City of Oakland – Leona Quarry

<b>Date:</b>	October 7th, 2005; 9:30 a.m. – 11:00 a.m.	
<b>Inspector:</b>	Vanessa Loverti (Essex Environmental)	
<b>Weather:</b>	Sunny, approximately 70 degrees Fahrenheit, and winds approximately 0 to 5 mph.	

**ACTIVITY:** Whipsnake Fence Inspection

Inspected the entire continuous line of fence in the Ridgmont Basin as well as the two separate fences along Campus Drive. The fence in the Ridgmont Basin is in need of repair due to recent construction activities. De Silva and Gates has been informed of this situation. Other than the repair to the fence in the Ridgmont Basin, the remaining fence complied with the requirements of the project special Status Species Mitigation and Monitoring Plan.

The Herp fence was removed from the Northwestern slope to the Access Road along 580. All of the work in this area has been completed and the requirements for removing the herp fence have been met (for this section of fence only). All the roads in this area have been paved, slopes stabilized and seeded.