



Essex Environmental, Inc.

## ENVIRONMENTAL COMPLIANCE STATUS REPORT

### City of Oakland – Leona Quarry

<b>Date:</b>	November 4th, 2005; 9:00 a.m. – 10:30 a.m.	
<b>Inspector:</b>	Vanessa Loverti (Essex Environmental)	<i>Vanessa Loverti</i>
<b>Weather:</b>	Sunny, approximately 70 degrees Fahrenheit, and winds approximately 0 to 5 mph.	

**ACTIVITY:** Whipsnake Fence Inspection

Inspected the entire continuous line of fence in the lower quarry as well as the two separate fences in the upper quarry along Campus Drive. The northern most fence along Campus Drive has two large holes. The damage is adjacent to a newly installed v-ditch. This observation was pointed out to De Silva and Gates for repair. All other fencing complied with the requirements of the project special Status Species Mitigation and Monitoring Plan.

An additional length of fencing is proposed to extend above a retaining wall, which will be constructed adjacent to the Ridgemont Basin. It is recommended that this additional fencing be installed prior to removing the fence along the steep slopes to discourage wildlife from entering the work area.