




Essex Environmental, Inc.

ENVIRONMENTAL COMPLIANCE STATUS REPORT

City of Oakland – Leona Quarry

Date:	December 8, 2005; 9:15 a.m. – 11:30 a.m.	
Inspector:	Lincoln Allen (Essex Environmental)	
Weather:	Mostly cloudy, approximately 58 degrees Fahrenheit, and winds approximately 0 to 8 mph.	

ACTIVITY: Whipsnake Fence Inspection

The entire continuous line of fence in the lower quarry, as well as the two separate fences in the upper quarry at Campus Drive (one located at the western terminus, and the other at the eastern terminus of the construction area) were inspected. Overall, the lower and upper quarry fencing complied with the requirements of the project's Special Status Species Mitigation and Monitoring Plan (SSSMMP). However, the western upper-quarry fence contains a hole where a fire hose intersects and extends beneath the fencing along the downhill terminus of the fence. This breach (which appears to have been recently mended, but has subsequently re-opened) could facilitate the movement of animals into construction areas, and should be mended. Noteworthy is the fact that repairs had been made where requested since the time of the last inspection.

ACTIVITY: Communication

The above findings were communicated to Peter Helseth, as well as Jun Osalbo. Peter informed me that a crew would re-mend the breach in the upper/west fence as soon as possible.