



Essex Environmental, Inc.

## ENVIRONMENTAL COMPLIANCE STATUS REPORT

### City of Oakland – Leona Quarry

<b>Date:</b>	December 20, 2005; 11:00 a.m. – 12:00 a.m.	
<b>Inspector:</b>	Vanessa Loverti (Essex Environmental)	<i>Vanessa Loverti</i>
<b>Weather:</b>	Mostly cloudy, approximately 62 degrees Fahrenheit, and winds approximately 0 to 5 mph.	

**ACTIVITY:** Whipsnake Fence Inspection

The entire continuous line of fence in the lower quarry, as well as the two separate fences in the upper quarry at Campus Drive (one located at the western boundary, and the other at the eastern boundary of the construction area) were inspected. Overall, the lower and upper quarry fencing complied with the requirements of the project's Special Status Species Mitigation and Monitoring Plan (SSSMMP). However, the western upper-quarry fence contains a section of fence that is no longer buried in addition to a section of fence that needs tightening. These areas were flagged and De Silva and Gates was informed of the needed repairs.

**ACTIVITY:** Communication

I spoke briefly with Peter Helseth and Jun Osalbo about the frequency of herp fence inspections during the winter and estimated completion of the retaining wall adjacent to the Ridgemont Basin.